

OFFICE ENGINEER NPP SIYANA DISTRICT BULANDSHAHAR

S.NO. १०८ | १०८ | 2022

DATE ९-३-२०२२

BUILDING SAFETY CERTIFICATE

It is certified that the building of CHANDRAWATI PUBLIC SCHOOL SIYANA is in good condition to run a school. Inspection is done by engineer of nagar palika parishad siyana distt. Bularidshahr and made the report that school is safe to run school.

Therefore NPP siyana is issuing building safety certificate to chandrawati public school siyana for the next five years.

Office Engineer:

लोकेशारी अधिकारी
नगर पालिका परिषद
Nagar palika parishad
Siyana (Bulandshahar)

कार्यालय सहायक अभियन्ता

निर्माण खण्ड-2, लोक निर्माण विभाग, बुलन्दशहर

प्रमाण-पत्र

पत्रांक :- Comp

दिनांक 24/6/24

प्रमाणित किया जाता है कि चन्द्रावती पब्लिक स्कूल, बुगरासी रोड, स्याना, जनपद बुलन्दशहर का निरीक्षण श्री रजनीश कुमार त्यागी, अवर अभियन्ता द्वारा दिनांक 24.05.2024 को किया गया। उक्त भवन में भू-तल एवं प्रथम-तल है। भवन 'नैशनल बिल्डिंग कोड-2005 के सुरक्षा प्राविधानों के अनुरूप है। उक्त भवन का निर्माण D.S. Teotia, Civil Draftman Lic. No. 12/7603, N.P.P. Syana (Bulandshahar) की देख-रेख में किया गया है। उक्त भवन प्रथम दृष्टया सुरक्षित है।

Wala Sy. B.P.T.
लोक निर्माण अभियन्ता
निर्माण खण्ड-2, बुलन्दशहर
उत्तर प्रदेश, भारत